Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 10/3/2014	Man Days: 1
Inspection Unit: Peoria Persimmon St.	
Location of Audit: Pekin	
Exit Meeting Contact:	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Kevin Hecker	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
John Sigler	Quality Assurance Consultant	

	CUSTOMER METER & REGULATOR	Status
Category Comment:	<u>.</u>	
Meter sets observed were in	the following areas within Sunset Hills subdivision in Pekin:	
1501-1529 Glendale 2122-2125 Hillcrest 2203 Belmont 1503-1618 Highwood 1626-1631 Melanie		
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory
General Comment:		
All meter sets observed were	e in readily accessible locations.	

[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Satisfactory
General Comment:		
All regulators observed were p	rotected from the elements and insects with vent screens.	
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
General Comment:		
The regulator vent at 1515 Gle extending the regulator vent av	ndale was located near an exhaust/intake vent which appeared to be installed after meter set. This issuway from the opening.	ue will be corrected by
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Applicable
General Comment:		
No meter sets observed were i	in areas prone to flooding.	
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
General Comment:		
All meter sets observed were fi	irmly supported.	
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
General Comment:		
All customer regulators observ	ed vented to the outside atmosphere.	
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Satisfactory
General Comment:	·	
All customer services observed	d had service line valves upstream of the meter.	
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
General Comment:		
Underground service line valve	es were not checked as part of this audit.	
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Satisfactory
General Comment:	·	
Customer services that had be	en discontinued were pin locked in the off position.	
	CATHODIC PROTECTION	Status
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
AMEDEN II LINOIS COMBANI		

[192.465(a)]	Were pipe to soil readings taken?	Satisfactory
General Comment:		
Pipe to soil readings were take	en at the following locations:	
1501 Glendale:95 1503 Glendale:93 1508 Glendale:95 1511 Glendale: -1.05 1513 Glendale:96 1515 Glendale: -1.08 1516 Glendale:95 1519 Glendale: -1.03 1521 Glendale: -1.10 1524 Glendale:95 1529 Glendale: -1.12		
1626 Melanie: -1.02 1629 Melanie: -1.14 1631 Melanie: -1.15		
2122 Hillcrest: -1.08 2123 Hillcrest: -1.06 2124 Hillcrest: -1.14 2125 Hillcrest: -1.10		
1503 Highwood:94 1507 Highwood:98 1509 Highwood:94 1515 Highwood: -1.12 1602 Highwood: -1.11/-1.13 (2 1603 Highwood: -1.16 1605 Highwood: -1.15 1613 Highwood: -1.08 1618 Highwood: -1.05	r meters)	
[192.465(b)]	Were rectifier installations inspected?	Satisfactory
General Comment: Staff inspected a rectifier locat	ed at 18058 Unsicker Road.	
[192.465(a)]	Were isolated mains/services tested?	Not Checked
General Comment:	•	
No isolated mains/services we	re checked as part of this audit.	
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
General Comment:	•	•
No bonds (critical or non-critical	al) were checked as part of this audit.	
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Satisfactory
General Comment:		

All customer meter sets obse	erved were isolated by use of an insulated meter spud.	
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
General Comment:	·	
No casings were inspected a	s part of this audit.	
[192.479(a)]	Is the above ground piping coated or painted as required?	Satisfactory
General Comment:	·	
Staff observed several farm t	aps at the following locations:	
Farm at Schmidt Road and R Farm on Schmidt Road and R 23180 Broadway Road 23128 Broadway Road 22946 Broadway Road Corner of Broadway and Uns	Route 5 (northeast corner) sicker Road (northwest corner) sicker Road (northeast corner)	
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Satisfactory
	DAMAGE PREVENTION	Status
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
General Comment:	·	
No activities requiring excava	ation were observed during this audit.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked
General Comment:	·	
No activities requiring excava	ation/locating were observed during this audit.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
General Comment:	<u> </u>	
No activities requiring excava	ation/locating were observed during this audit.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		

Staff observed line marke and Pekin.	ers over a transmission pipeline along Unsicker Road, north of Tremont, IL, Allentown Road and Queenwood F	Road between Tremont
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
General Comment:		
Staff observed line marke and Pekin.	ers over a transmission pipeline along Unsicker Road, north of Tremont, IL, Allentown Road and Queenwood F	Road between Tremont
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
General Comment:	<u> </u>	
Line markers were obser Road.	ved at the regulator station on Co. Road 2300 E just north of Tremont as well as a regulator station/rectifier sta	ation at 18058 Unsicker
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:	<u> </u>	
The line markers observe	ed at the above listed locations included the required information in the correct format.	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
General Comment:	<u> </u>	
One old line marker was a	identified at a culvert on Schmidt Road, just south of Allentown Road (Highway 5) This line marker contained mergency number still worked. Per the operator's O&M, all line markers must be updated by 12/2015.	the name of a legacy
PRESSU	JRE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Not Checked
General Comment:	<u> </u>	
Staff did not review regula station/rectifier station at	ator station inspection records, however, did inspect regulator stations on Co. Road 2300 E just north of Trem 18058 Unsicker Road.	ont as well as a regulator
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	

Both regulator stations observ	ed were protected from vehicular damage by steel barriers/fencing.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Checked
General Comment:		
No telemetering or recording g	gauges were included in this inspection.	
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Checked
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Staff did not inspect the overp	ressure protection valve at the take point.	
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:		
All supports observed were ma	ade of non-combustible material.	
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
General Comment:		
All regulator stacks observed to	were protected from the elements.	
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
General Comment:		
Staff inspected valves at and r Road.	near the regulator station at Co. Road 2300 E just north of Tremont as well as a regulator station/rectifier	station at 18058 Unsicker
	VALVE MAINTENANCE	Status
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Satisfactory
General Comment:		
Staff inspected valves at and r Road.	near the regulator station at Co. Road 2300 E just north of Tremont as well as a regulator station/rectifier	station at 18058 Unsicker
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Checked
General Comment:		
No blow down activities were	observed.	
	ODORIZATION OF GAS	Status

Category Comment:		
Inspection of odorization	equipment was not conducted as part of this audit.	
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
	TRANSMISSION	Status
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Satisfactory
[192.745(a)]	Were the valves inspected accessible?	Satisfactory
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Satisfactory
	MARKING OF MATERIAL	Status
Category Comment:		
Staff did not inspect surp	lus pipe and components.	
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
	OPERATOR QUALIFICATION	Status
Was a PHMSA Form	n 15 Operator Qualification Field Inspection Protocol Form completed?	No